

BIO ZAPP PAINT ODOR ELIMINATOR

MIXING INSTRUCTIONS for Refinishers Coatings

1. TOPCOAT / RESIN

(Any Acrylic Urethane colors including clear coats)

Add **2 ounces of PAINT ODOR ELIMINATOR** per gallon

(Epoxy primers add 1 ounce per gallon)

Mix / stir into coating, as usual, with paint stir stick

2. REDUCER / THINNER

Add **1 ounce of PAINT ODOR ELIMINATOR** per gallon

Shake container gently to mix thoroughly

3. CATALYST

DO NOT ADD PAINT ODOR ELIMINATOR

4. COMBINE-

Usual ratios of Topcoat / Catalyst / Reducer per job

5. PROCEED-

Spray coatings / No induction time is needed

Follow Coatings Manufacturers' Safety Precautions

6. EXCESS COATINGS-

Oxygen is the catalyst. Store leftover job material in an air-tight container, short term, for later use with continued results.